

UNCLASSIFIED

AD NUMBER

AD366717

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited

FROM:

Notice: Release only to U. S. Government Agencies is authorized. Other certified requesters shall obtain release approval from Director, Defense Atomic Support Agency, Washington, D. C. 20301.

AUTHORITY

DSWA ltr., 9 Apr 97; DSWA ltr., 9 Apr 97

THIS PAGE IS UNCLASSIFIED

XRB-31

CONFIDENTIAL

LIBRARY COPY NO. C-12

BUREAU OF SHIPS GROUP

TECHNICAL INSPECTION REPORT

CONFIDENTIAL

Classification (~~Confidential~~) (Changed to
By Authority of Joint Chiefs of Staff (Action 15 Apr 49)

By *James D. Butler* Date *24 Apr 51*

OPERATION CROSSROADS. U.S.S. INDEPENDENCE (CVL 22)

TEST ABLE.

VOLUME 2 OF 4 [10]

U. S. GOVERNMENT PRINTING OFFICE: 1947. THIS REPORT DIRECTLY
FROM DDC.

(11) 4947, (12) 250 P.
(14) XRB-31

Naval Mobile Support Agency
Washington, D. C. 20301

~~OPERATION CROSSROADS~~

DIRECTOR OF SHIP MATERIAL

JOINT TASK FORCE ONE

CONFIDENTIAL

TECHNICAL LIBRARY

of the

ARMED FORCES
SPECIAL WEAPONS PROJECT

NOV 2 1955

TJSA E

GROUP 3 1 JAN 1965
Downgraded at 12 year intervals;
Not automatically declassified.

REG. NO. *9624*

BUREAU OF SHIPS GROUP
TECHNICAL INSPECTION REPORT

CONFIDENTIAL

By *[Signature]* Date *24 Apr 51*
1st V.A. FOWP

U. S. GOVERNMENT
FROM USS INDEPENDENCE

NAVY AGENCY
WASHINGTON, D. C. 20301

APPROVED:
CONFIDENTIAL

F.X. Forest,
Captain, U.S.N.

NOTE: This volume contains
pages 1 to 250 inclusive.

SECRET


USS INDEPENDENCE (CVL22)

Page 1 of 766 Pages

GROUP 3
Downgraded at 12 year intervals
Not automatically declassified
JAN 1985

CONFIDENTIAL
ATOMIC ENERGY ACT 1946

[Illegible stamp]




BuShips #10968. Vertical aerial view before Test A showing guns and directors remaining for test.

SECRET

USS INDEPENDENCE (CVL22)

Page 2 of 766 Pages

9624




BuShips #5118. Broadside View-Starboard-Before Test A showing profile of ship before installation of special test equipment.

SECRET

USS INDEPENDENCE (CVL22)

Page 3 of 766 Pages

9624



BuShips #5117. Broadside View-Port-Before Test A-Showing profile of ship before installation of special test equipment.

SECRET

USS INDEPENDENCE (CVL22)

Page 4 of 766 Pages

9624



BA-CR-196-154-40. View from off port bow (before Test A).

SECRET

USS INDEPENDENCE (CVL22)

Page 5 of 766 Pages

9624



AA-CR-227-87-4. View of bow after Test A.

SECRET

USS INDEPENDENCE (CVL22)

Page 6 of 766 Pages

9624

AA-CR-196-154-39



AA-CR-196-154-39. Silhouette, from off starboard beam (before Test A).

SECRET

USS INDEPENDENCE (CVL22)

Page 7 of 766 Pages

9624



AA-CR-227-87-6. Broadside view-starboard-after Test A.

SECRET

USS INDEPENDENCE (CVL22)

Page 8 of 766 Pages

9624




BA-CR-196-154-38. Exterior view of starboard side from off starboard quarter, before Test A.

SECRET

USS INDEPENDENCE (CVL22)

Page 9 of 766 Pages

9624



AA-CR-227-87-1. View of starboard side after Test A taken from abaft the beam.

SECRET

USS INDEPENDENCE (CVL22)

Page 10 of 766 Pages

9624




BA-CR-196-154-37. Exterior view from dead astern (before Test A).

SECRET

USS INDEPENDENCE (CVL22)
Page 11 of 766 Pages

9624



AA-CR-227-87-5. View of stern after Test A.

SECRET

USS INDEPENDENCE (CVL22)
Page 12 of 766 Pages

9624


SECRET



AA-CR-196-154-36. General view from port quarter (before Test A).

SECRET

USS INDEPENDENCE (CVL22)
Page 13 of 766 Pages




AA-CR-227-87-2. View of after port quarter after Test A.

SECRET

USS INDEPENDENCE (CVL22)

Page 14 of 766 Pages

9624



BA-CR-196-154-35. Exterior view, from off port beam (before Test A).

SECRET

USS INDEPENDENCE (CVL22)
Page 15 of 766 Pages

9624




AA-CR-227-92-97. Broadside view-port-after Test A.

SECRET

USS INDEPENDENCE (CVL22)
Page 16 of 766 Pages

9624



AA-CR-68-1745-12. Smoke on Independence.

SECRET

Page 17 of 766 Pages

USS INDEPENDENCE (CVL22)

9624



AA-CR-62-1808-6. Flare-up on stern of INDEPENDENCE, probably due to low order detonation in torpedo stowage, viewed from starboard at H-hour plus 5 2/3.

SECRET

USS INDEPENDENCE (CVL22)

Page 18 of 766 Pages

9624




AA-CR-80-1893-4. Flare-up on stern of INDEPENDENCE, probably due to low order detonation in torpedo stowage, viewed from starboard a few minutes after 1808-6.

SECRET

USS INDEPENDENCE (CVL22)

Page 19 of 766 Pages

9624.



AA-CR-80-1893-5. Fire in way of after elevator viewed from starboard.

SECRET

USS INDEPENDENCE (CVL22)

Page 20 of 766 Pages

9624



A CR79-1810-

AA-CR-79-1810-4. View of Independence from starboard.

SECRET

Page 21 of 766 Pages

USS INDEPENDENCE(CVL22)

9624



A CR **79**- 1810-

AA-CR-79-1810-5. View of Independence from starboard.

SECRET

USS INDEPENDENCE (CVL-22)

Page 22 of 766 Pages

9624



A CR **79**- 1810-


AA-CR-79-1810-6. View of Independence from starboard.

SECRET

USS INDEPENDENCE(CVL22)

Page 23 of 766 Pages

9624



A CR 79-1810-

AA-CR-79-1810-7. View of Independence from starboard.

SECRET

Page 24 of 766 Pages

USS INDEPENDENCE (CVL22)

167CR62-1832-


AA-CR-62-1832-7. View from port quarter, stern still smoking, see 1808-6, 1893-5.

SECRET

USS INDEPENDENCE (CVL22)
Page 25 of 766 Pages ,

9624

AA CR 62-1859 +



AA-CR-62-1859-8. After section viewed from off port quarter, fire still burning on stern (see 1893-4).

SECRET

USS INDEPENDENCE (CVL22)
Page 26 of 766 Pages

9624



AB CR 79-4066 -

AB-CR-79-4066-8. After Baker - Stern view of Independence.

SECRET

Page 27 of 766 Pages

USS INDEPENDENCE(CVL22)

9624




AA-CR-59-2112-9. Port side. Distant view of Independence after Test A.

SECRET

Page 28 of 766 Pages

USS INDEPENDENCE (CVL22)

9624



CR 60-1713

AB-CR-60-1713-11. View of bow from dead ahead.

SECRET

Page 29 of 766 Pages

USS INDEPENDENCE(CVL22)

9624

ABCR 79-4067




AB-CR-79-4067-1. After Baker. Starboard bow view, bow to frame 25.

SECRET

Page 30 of 766 Pages

USS INDEPENDENCE(CVL22)

9624



AA-CR-65-1736-10. Starboard shell between Bow and frame 22 showing denting of top of sheer strake between frames 9 and 18, and, diagonal wrinkling between frames 12 and 16.

SECRET

USS INDEPENDENCE (CVL22)
Page 31 of 766 Pages

9624



AB CR60 - 1712 - 8


AB-CR-60-1712-8. Starboard shell, frame 35 to bow.

SECRET

USS INDEPENDENCE (CVL22)

Page 32 of 766 Pages

9624



AB-CR-79-4066-2. After Baker. Starboard view, frames 22 to 54.

SECRET

Page 33 of 766 Pages

USS INDEPENDENCE (CVL-22)

9624



ABCR 79-4066 -


AB-CR-79-4066-3. After Baker. Starboard view, frames 40 to 54.

SECRET

Page 34 of 766 Pages

USS INDEPENDENCE (CVL22)

9624



ABCR 79-4066 -


AB-CR-79-4066-4. After Baker. Starboard view, frames 68 to 103.

SECRET

Page 35 of 766 Pages

USS INDEPENDENCE(CVL22)

9624




AB-CR-60-1710-11. Looking forward along starboard shell from frames 130 to 80, Note shear wrinkles in shell plating along water line in way of frame 130, (see, also, 1713-4).

SECRET

Page 36 of 766 Pages

USS INDEPENDENCE (CVL22)

9624



3 CR 60-1713-1

AB-CR-60-1713-1. Looking forward along starboard shell from point off starboard quarter.

SECRET

Page 37 of 766 Pages

USS INDEPENDENCE(CVL22)

9624



AB-CR-60-1712-12

AB-CR-60-1712-12. Starboard shell, frames 120-90, looking to port.

SECRET

USS INDEPENDENCE (CVL22)

Page 38 of 766 Pages

9624



AB CR 79 4066 -

AB-CR-79-4066-5. After Baker. Starboard view, frames 100 to 139.

SECRET

Page 39 of 766 Pages

USS INDEPENDENCE(CVL22)


9524



SECRET

Page 40 of 766 Pages

9624



AB CR 79-4066 -

AB-CR-79-4066-6. After Baker. Starboard quarter, frames 116 to stern.

SECRET

Page 41 of 766 Pages

USS INDEPENDENCE (CVL22)

9624




AA-CR-59-2087-7. Starboard after quarter showing shear wrinkles below third deck between frames 120-140.

SECRET

USS INDEPENDENCE (CVL22)

Page 42 of 766 Pages

9624



ACR 59-2087

AA-CR-59-2087-6. View of starboard quarter.

SECRET

USS INDEPENDENCE (CVL22)

Page 43 of 766 Pages

9624



10 CR60-1710-


AB-CR-60-1710-10. View of stern and after starboard section from off starboard quarter.

SECRET

USS INDEPENDENCE(CVL22)

Page 44 of 566 Pages

9624



AA CR 59-2087

AA-CR-59-2087-5. Damage to after 40 M/M sponson. Note lower port corner of transom. Starboard quarter showing.

SECRET

USS INDEPENDENCE (CVL22)
Page 45 of 766 Pages

9624




AB-CR-68-2981-4. After Baker. General view of starboard side, looking forward from frame 36.

SECRET

USS INDEPENDENCE (CVL22)
Page 46 of 766 Pages

9624



AA-CR-65-1736-11. Starboard shell between frames 14 and 27 showing opposing diagonal wrinkles.

SECRET

USS INDEPENDENCE (CVL22)
Page 47 of 766 Pages

9624



AB-CR-60-1710-12. Starboard shell frames 40 to 20 and overhanging structure.

SECRET

Page 48 of 700 Pages

USS INDEPENDENCE (CVL22)

9624



AA-CR-59-4148-1. General view of starboard shell, frames 115-133.
Shell wrinkle can be seen above propeller guard.

SECRET

USS INDEPENDENCE (CVL22)
Page 49 of 766 Pages

9624



AA-CR-71-2073-2. Starboard shell, frames 120 to 137. Note wrinkles in shell below third deck at waterline.

SECRET

Page 50 of 766 Pages

USS INDEPENDENCE (CVL22)

9624



CR-62-1860 -


AA-CR-62-1860-9. Independence - Damage to bow.

SECRET

USS INDEPENDENCE(CVL22)

Page 51 of 766 Pages

9624



AA CR 62-1860-10.

AA-CR-62-1860-10. Port side damage from off port bow.

SECRET

Page 52 of 766 Pages

USS INDEPENDENCE(CVL22)

9624




AA-CR-62-1860-8. After section viewed from off port quarter.

SECRET

USS INDEPENDENCE(CVL22)

Page 53 of 766 Pages

9624



1A CR **62**-1860 -|


AA-CR-62-1860-7. After section viewed from off port quarter.

SECRET

USS INDEPENDENCE (CVL22)

Page 54 of 766 Pages

9624



AB-CR-221-353-25. Forward port shell area, view from off port bow.

SECRET

USS INDEPENDENCE (CVL22)

Page 55 of 766 Pages

9624



AB-CR-221-353-24. Forward port hull area, viewed from off port bow.

SECRET

Page 56 of 766 Pages

USS INDEPENDENCE (CVL22)

9624



AB-CR-221-353-23. Forward port shell area, viewed from off port beam.

SECRET

Page 57 of 766 Pages

USS INDEPENDENCE(CVL22)

9624




AB-CR-221-353-22. Forward port shell and hangar cover plating viewed from off port beam.

SECRET

USS INDEPENDENCE (CVL22)

Page 58 of 766 Pages

9624



AB-CR-221-353-21. Damage to shell and hangar cover plating looking forward and to starboard from off port beam

SECRET

Page 59 of 766 Pages

USS INDEPENDENCE(CVL22)

9624



AB-CR-221-353-20. Damage to port shell and hangar cover plating, looking forward and to starboard, from off port quarter. Note washboarding of shell plating between frames.

SECRET

Page 60 of 766 Pages

USS INDEPENDENCE(CVL22)

9624



AB-CR-221-353-19. Damage to port shell and hangar cover plating, "looking forward and to starboard, from off port quarter."

SECRET

Page 61 of 766 Pages

USS INDEPENDENCE (CVL-22)

9624



AB CR 79-2973 -

AB-CR-79-2973-3. After Baker. Bow view.

SECRET

USS INDEPENDENCE (CVL22)

Page 62 of 766 Pages

9624



AB-CR-79-4068-6


AB-CR-79-4068-6. After Baker. Bow view, bow to frame 18.

SECRET

USS INDEPENDENCE(CVL22)

Page 63 of 766 Pages

9624



AB CR 60-1713 -

AB-CR-60-1713-8. Port side damage from frames 20 to 50.

SECRET

USS INDEPENDENCE(CVL22)

Page 65 of 766 Pages

9624




AB-CR-60-1713-10. Port side damage to overhanging structure, failure of cover panels in way of hangar deck and extreme dishing of shell between longitudinal aft, looking aft from port bow,

SECRET

USS INDEPENDENCE (CVL22)

Page 66 of 766 Pages

9624




AB-CR-60-1713-7. Port side damage from frames 40 to 80.

SECRET

USS INDEPENDENCE(CVL22)

Page 67 of 766 Pages

9624



98 CR 60-1713-6

AB-CR-60-1713-6. Port side damage, frames 60 to 90 from off port beam. Note shear wrinkle in shell superimposed upon longitudinal dishing.

SECRET

USS INDEPENDENCE (CVL22)

Page 68 of 766 Pages

9624



AB-CR-60-1713-5. Port side damage, frames 80 to 120. Light sheet metal cover panels enclosing hangar space have been carried away, both port and starboard badly buckled bents are in way of flight deck expansion joints.

SECRET

USS INDEPENDENCE (CVL22)

Page 69 of 766 pages

9624




AB-CR-60-1713-4. Port side damage, frames 110 to 140. Note overhanging structure is essentially carried away and structure aft generally mangled.

SECRET

Page 70 of 766 Pages

USS INDEPENDENCE (CVL22)

9624



AB-CR-60-1713-3. Looking to starboard from off port quarter at severe damage to stern.

SECRET

Page 71 of 766 Pages

USS INDEPENDENCE (CVL22)

9624



AB CR 79 - 2973 -


AB-CR-79-2973-2. After Baker. View of port quarter.

SECRET

USS INDEPENDENCE (CVL22)

Page 72 of 766 Pages

9624



AA^{CR} 71-2073 -|

AA-CR-71-2073-12. Port bow, bow to frame 22, showing blistered paint and slightly dished shell plating.

SECRET

USS INDEPENDENCE (CVL22)
Page 73 of 766 Pages

9624



AB-CR-79-4068-5

AB-CR-79-4068-5. After Baker. Port shell, frame 7 to 33.

SECRET

USS INDEPENDENCE (CVL22)
Page 74 of 766 Pages

9624




AB-CR-79-4069-4. After Baker. Port side, frames 23 to 50.

SECRET

USS INDEPENDENCE (CVL22)
Page 75 of 766 Pages

9624




AB-CR-79-4068-3. After Baker. Port side, frames 48 to 77.

SECRET

USS INDEPENDENCE (CVL-22)
Page 76 of 766 Pages

9624



AB-CR-79-4068-2. After Baker. Port side, frames 68 to 98.

SECRET

USS INDEPENDENCE (CVL22)
Page 77 of 766 Pages

9624




AA-CR-59-2086-12. General view of damage to port side between frames 71 and 95. Note backward curve of column at frame 83.

SECRET

USS INDEPENDENCE (CVL32)

Page 78 of 766 Pages

9624



AA-CR-59-2087-1. General view of damage to port side between frames 89 and 115. Shows opening in flight deck expansion joint frame 111 1/2; and, blister shell damage.

SECRET

USS INDEPENDENCE (CVL22)

Page 79 of 766 Pages

9624



AA-CR-71-2073-6. Port shell, frames 90 to 113. Note dished blister shell plating and damaged flight decks bents.

SECRET

USS INDEPENDENCE (CVL22)

Page 80 of 766 Pages

9624




AA-CR-71-2073-5. Port side, frames 103 to 128. Note damaged flight deck, missing after elevator, and general damage to shell both above and below the main deck.

SECRET

USS INDEPENDENCE (CVL22)

Page 81 of 766 Pages

9624



AA-CR-71-2073-4. Port side, frames 119 to 148, showing severe blast damage.

SECRET

USS INDEPENDENCE (CVL22)
Page 82 of 766 Pages

9624




AA-CR-59-2087-2. General view of damage to port quarter, frames 118 to 146.

SECRET

USS INDEPENDENCE (CVL22)
Page 83 of 766 Pages

9624



AA-CR-71-2073-3. Port quarter, frame 134 to stern.

SECRET

USS INDEPENDENCE (CVL22)
Page 84 of 766 Pages

9624



AA-CR-59-2216-2. General view of damage to port quarter, from frame 115 to stern. Note shelf along 3rd deck level aft of frame 128.

SECRET

USS INDEPENDENCE (CVL22)
Page 85 of 766 Pages

9624




AA-CR-59-2216-1. Port quarter, frame 118 to stern.

SECRET

USS INDEPENDENCE (CVL22)

Page 86 of 766 Pages

9624




AA-CR-71-2073-10. Port shell, frames 50 to 53, showing wrinkled and dished blister plating.

SECRET

USS INDEPENDENCE (CVL22)
Page 87 of 766 Pages

9624



AA-CR-59-2086-11. Port side between frames 40 and 75 showing remaining gallery structure tipped up, voids between flight deck bent columns (where hangar side plating was blown away), and the deep dishing of the shell aft of frame 66.

SECRET

USS INDEPENDENCE (CVL22)

Page 88 of 766 Pages



AA-CR-65-1734-11. Blast damage to port side between frames 59 and 80. Note gallery walkway, backward curve of Wobble Bent No. 62 and dishing of shell between main, 2nd and 3rd deck.

SECRET

USS INDEPENDENCE (CVL22)

Page 89 of 766 Pages

9624




AA-CR-71-2072-12. Port shell frames 62 to 78, showing wrinkled and dished blister plating.

SECRET

USS INDEPENDENCE (CVL22)

Page 90 of 766 Pages

9624




AA-CR-71-2073-8. Port side, frames 62 to 83, showing damaged hangar side plating and wrinkled and dished blister plating.

SECRET

USS INDEPENDENCE (CVL22)

Page 91 of 766 Pages

9624



AA-CR-71-2073-7. Port side, frames 71 to 92, showing dished and wrinkled blister plating.

SECRET

USS INDEPENDENCE (CVL22)

Page 92 of 766 Pages

9624



AA-CR-71-2072-11. Port side, frames 87 to 107, showing damage above main deck, and dished and wrinkled blister plating.

SECRET

USS INDEPENDENCE (CVL22)

Page 93 of 766 Pages

9624




AA-CR-71-2072-10. Port side, frames 115 to 139, showing dished shell plating and severe damage aft of frame 132.

SECRET

USS INDEPENDENCE (CVL22)
Page 94 of 766 Pages

9624



AA-CR-59-2216- 3. General view of port side damage between frames 115 and 140. Note maze of wreckage aft of frame 126, depression below 3rd deck between frames 126 and 133 and numerous plate tears.

SECRET

USS INDEPENDENCE (CVL22)

Page 95 of 766 Pages

9624



AA-CR-71-2072-9. Port quarter view showing severe damage from frame 130 to stern.

SECRET

USS INDEPENDENCE (CVL22)

Page 96 of 766 Pages

9624



AA-CR-71-2072-8. Port quarter view showing severe damage from frame 140 to stern.

SECRET

USS INDEPENDENCE (CVL22)

Page 97 of 766 Pages

9624




AA-CR-59-2166-3. General view of blast damage to port shell between frames 55 and 70. Note slight dishing of shell panels aft of frame 65. (This dishing measured about 6" in depth).

SECRET

USS INDEPENDENCE (CVL22)

Page 98 of 766 Pages

9624



AA-CR-59-2166-4. General view of damage to port side between frames 75 and 88 looking aft. Dishing shown measures between 9'' and 12'' at frame 83. Note also, tear at frame 83 above 3rd deck.

SECRET

USS INDEPENDENCE (CVL22)

Page 99 of 766 Pages

9624



AA-CR-59-2166-5. General view of damage to port side between frames 75 and 88 looking forward. For view looking aft see 2166-4.

SECRET

USS INDEPENDENCE (CVL22)

Page 100 of 766 Pages

9624



AA-CR-59-2166-6. General view of damage along port side between frames 92 and 101. Note dishing of blister shell under hose between frames 96 and 97.

SECRET

USS INDEPENDENCE (CVL22)
Page 101 of 766 Pages

9624



AA-CR-59-2166-7. View of blister-top and shell-port side-between frames 100 and 106. Measured deflections in shell at frame 104 were 9'' and 14'' maximum.

SECRET

USS INDEPENDENCE (CVL22)

Page 102 of 766 Pages

9624




AA-CR-59-2166-8. General view between frames 108 and 120 port side.

SECRET

USS INDEPENDENCE (CVL22)
Page 103 of 766 Pages

9624



AA-CR-59-2166-9. General view of damage to port side between frames 108 and 128. Depressions are moderate but can be seen plainly. Note condition of Wobble Bents 110 and 113.

SECRET

USS INDEPENDENCE (CVL22)

Page 104 of 766 Pages

9624



AA-CR-59-2217-4

AA-CR-59-2217-4. View looking down on port shell between frames 120 and 128. Propeller guards between frames 123 and 125.

SECRET

USS INDEPENDENCE (CVL22)

Page 105 of 766 Pages

9624



AA-CR-59-2217-5. Looking down on port side at third deck, aft of frame 132, from catwalk.

SECRET

USS INDEPENDENCE (CVL22)

Page 106 of 766 Pages

9624



AA-CR-59-2217-3. View of port shell, looking into shipfitters shop, from gallery level, frame 130. Note plating tears and failure along seam at main and 3rd deck levels.

SECRET

USS INDEPENDENCE (CVL22)

Page 107 of 766 Pages

9624



AA-CR-59-2166-10. General view of port after quarter, looking aft from flight deck. Note port shell folded over at third deck level and plating failures along welded seams.

SECRET

USS INDEPENDENCE (CVL22)

Page 108 of 766 Pages

9624




AA-CR-71-2073-11. Port shell, frames 23 to 39, showing shell plating slightly dished.

SECRET

Page 109 of 766 Pages

USS INDEPENDENCE (CVL22)

9624




AA-CR-65-1734-9. General view of damage to port side between frames 71-88. Note heavy dishing of hangar side plating frames 71-74; and, deformation of columns to flight deck bents. Bitts are at frame 74.

SECRET

USS INDEPENDENCE (CVL22)

Page 110 of 766 Pages

9624



AA-CR-65-1734-7. Damage to port side between frames 89 and 101.

SECRET

USS INDEPENDENCE (CVL22)
Page 111 of 766 Pages

9624



AA-CR-65-1734-5. Detail view of port shell between frames 106 and 116. Note sharp depression under Wobble Bent at frame 110, tear along weld at stringer at frame 113, and general washboard appearance of shell.

SECRET

USS INDEPENDENCE (CVL-22)

Page 113 of 766 Pages

9624



AB-CR-68-2948-6. After Baker. Detail view of port side, frames 108-115.

SECRET

USS INDEPENDENCE (CVL22)
Page 113 of 766 Pages

9624



AB-CR-68-2948-7. After Baker. Detail view of port side, frames 112 to 117.

SECRET

USS INDEPENDENCE (CVL22)
Page 114 of 766 Pages

9624



AA-CR-59-2087-3. General view of port shell between frames 118 and 137. Note that 3rd. deck is pushed up in way of depression, frames 126 to 132, between waterline and 3rd. deck.

SECRET

USS INDEPENDENCE (CVL22)

Page 115 of 766 Pages

9624




AA-CR-59-2216-4. Detail view of port shell between frames 115 and 128. Note deep depression below third deck and aft of frame 126.

SECRET

USS INDEPENDENCE (CVL22)

Page 116 of 766 Pages

9624




AB-CR-68-2949-3. After Baker. Port side, frame 115 to 126.

SECRET

Page 117 of 766 Pages

USS INDEPENDENCE (CVL22)

9624



AA-CR-65-1734-3. Detail of port shell between frames 123 and 132.
Note tear in shell just under 3rd deck.

SECRET

USS INDEPENDENCE (CVL22)
Page 118 of 766 Pages

9624



AA-CR-65-1734-1. Blast damage on port side between 3rd deck and poop deck, frames 135 to 147. Note that light side plating at main deck is torn loose and main deck is folded down over the shell plating.

SECRET

USS INDEPENDENCE (CVL22)
Page 119 of 766 Pages

9624



AA CR 93 - 1999

AA-CR-93-1999-8. Exterior view showing blast damage to port shell between main and 3rd decks and forward of frame 140. Note failure of welded horizontal seam at main deck level at upper right, and line of 3rd deck at lower left. Looking forward.

SECRET

USS INDEPENDENCE (CVL22)

Page 120 of 766 Pages



AA-CR-175-2117-10. Exterior view showing blast damage to port shell between main and 3rd decks and forward of frame 140. Note buckling of transverse bulkhead 138 (painted white), and failure of welded horizontal seam at main deck. (Located at level of inspectors hands). Looking forward.

SECRET

USS INDEPENDENCE (CVL22)

Page 121 of 766 Pages

9624




AA CR 59-2216

AA-CR-59-2216-12. General view of port after quarter. Note twisting of lower port after corner of transom.

SECRET

USS INDEPENDENCE (CVL22)
Page 122 of 766 Pages

9624



AA-CR-175-2117-12. Port shell as seen from about frame 142, looking --
aft and up. Note curling of main deck plating down and under, and general
disruption of shell structure.

SECRET

USS INDEPENDENCE (CVL22)

Page 123 of 766 Pages

9624



AA-CR-93-1999-7. View from about second deck level, looking aft from frame 130, showing damage to port shell, main and second decks.

SECRET

USS INDEPENDENCE (CVL22)

Page 124 of 766 Pages

9624



AA-CR-175-2117-11. Port shell, frames 144 and aft, second deck level, showing tear in welded seam.

SECRET

USS INDEPENDENCE (CVL22)

Page 125 of 766 Pages

9624



AA CR 59-2216 .

AA-CR-59-2216-9. Detail view of port after quarter.

SECRET

USS INDEPENDENCE (CVL22)
Page 126 of 766 Pages

9624



AA CR 59-2216 -


AA-CR-59-2216-11. View at stern, looking forward along port side. Note portion of main deck between frames 144 and 146 still connected to side plating. Top and bottom seams of aft gun sponson are opened. Main deck is folded downward and inward.

SECRET

USS INDEPENDENCE (CVL22)

Page 127 of 766 Pages

9624



AB-CR-65-1733-11. View of damage to port side at stern. Note tears in plating and effect of blast on lower port corner of transom.

SECRET

USS INDEPENDENCE (CVL22)

Page 128 of 766 Pages

9624




AA-CR-59-2216-10. View showing dishing of transom and sponson.
Note failure along welded seams of sponson.

SECRET

USS INDEPENDENCE (CVL22)

Page 129 of 766 Pages

9624



AA-CR-59-2227-9. Looking forward from frame 39 along port shell above forecastle deck, showing slight panel deflections and shadow line from heat wave.

SECRET

USS INDEPENDENCE (CVL22)

Page 130 of 766 Pages

9624




AA-CR-59-2227-8. Looking forward from frame 45 along port shell above forecastle deck showing dished door panel and scarred paint not caused by fire.

SECRET

USS INDEPENDENCE (CVL22)

Page 131 of 766 Pages

9624



AA CR 65 - 10

AA-CR-65-1734-10. Blast damage to flight deck, walkway and sponson on port side forward of frame 84.

SECRET

USS INDEPENDENCE (CVL22)
Page 132 of 766 Pages

0000



1 (T) 65 - 1734-8


AA-CR-65-1734-8. Damaged flight deck bents between frames 80 and 95, gallery walkway and spansons. Note opening of expansion joint, frame 84 1/2.

SECRET

USS INDEPENDENCE (CVL22)

Page 133 of 766 Pages

9624



AA-CR-65-1734-6. Damaged flight deck bents between frames 104 and 115, gallery walkway and sponsons. Note opening of expansion joint, frame 111 1/2.

SECRET

USS INDEPENDENCE (CVL33)

Page 134 of 766 Pages

9624




AA-CR-65-1734-4. Detail view of port side damage, frame 115-126, above main deck. Note curvature of column at frame 118, condition of gallery walkway and deformation of antennae mast.

SECRET

USS INDEPENDENCE (CVL22)

Page 135 of 766 Pages

9624



AA-CR-59-2216-5. General view of damage above second deck, port side, frames 120 to 136.

SECRET

USS INDEPENDENCE (CVL22)
Page 136 of 766 Pages

9624




AA-CR-59-2216-6. Tear in port shell above main deck at bulkhead 132, and general disruption of structure between frames 131 and 137.

SECRET

USS INDEPENDENCE (CVL22)
Page 137 of 766 Pages

9624




AA-CR-59-2113-2. Boat handling structure port side, hangar deck level, frames 124 to 129, showing deformation of structure and weld failures at T-joint connections. Looking aft.

SECRET

USS INDEPENDENCE (CVL22)

Page 138 of 766 Pages

9624



AA-CR-2113-1. Boat handling structure, port side, hangar deck level, frames 124 to 129, showing deformation of members and weld failures at T-joint connections. Looking aft.

SECRET

USS INDEPENDENCE (CVL32)

Page 139 of 766 Pages

9624



AA-CR-175-2217-1. Boat handling structure and port shell, hangar deck level, frames 125 to 128, showing deformation of structure and failure of welded joints. Looking forward and toward starboard.

SECRET

USS INDEPENDENCE (CVL22)

Page 140 of 766 Pages

9624



AA-CR-175-2115-1. Port side plating torn at poop deck level, about frame 128 showing poop deck plating in radio repair shop.

SECRET

USS INDEPENDENCE (CVL22)

Page 141 of 766 Pages

9624



AA-CR-59-2217-2. Port shell aft of bulkhead 132, looking aft and down from hangar level catwalks.

SECRET

USS INDEPENDENCE (CVL22)

Page 142 of 766 Pages

9624



AA-CR-175-2041-2. Blast damage to flight and poop decks and after superstructure side plating. Note that flight deck and overhang has been carried away poop deck buckled. Failure of welded joints in side plating. Frames 140 to 144, looking aft on port side.

SECRET

USS INDEPENDENCE (CVL22)

Page 143 of 766 Pages

9624




AA-CR-59-2216-7. General view of damage to port after quarter. Note tear in port shell along main deck and folding down of deck aft of bulkhead 138. Flight deck corner missing.

SECRET

USS INDEPENDENCE (CVL22)

Page 144 of 766 Pages

9624




AA-CR-65-1734-2. Blast damage above second deck port side, frames 134 to 147.

SECRET

USS INDEPENDENCE (CVL22)
Page 145 of 766 Pages

9624



AA-CR-59-4148-2. Port side, looking aft, gallery level. Note twisted flight deck beams and damaged side plating.

SECRET

USS INDEPENDENCE (CVL22)

Page 146 of 766 Pages

9674



LA CR 59-2087

AA-CR-59-2087-4. General view of damage to port after quarter.

SECRET

USS INDEPENDENCE (CVL22)

Page 147 of 766 Pages

9624




AA-CR-59-2216-8. Port side, aft of frame 140, above third deck level. Note tears at second and third deck levels, and splitting of shell below main deck at frame 145.

SECRET

USS INDEPENDENCE (CVL22)

Page 148 of 766 Pages

9624




AA-CR-65-1733-12. Port side plating aft of frame 144 above main deck.

SECRET

USS INDEPENDENCE (CVL22)
Page 149 of 766 Pages

9624



AB-CR-79-2964-1. After end of flight deck, looking down and to port from point off starboard quarter.

SECRET

USS INDEPENDENCE (CVL22)
Page 150 of 766 Pages

9624



AB-CR-79-2964-2. Flight deck in way of after elevator, frames 110 to 150, looking down and to port from point off starboard side. Note effects of fire on deck aft of elevator well.

SECRET

USS INDEPENDENCE (CVL22)

Page 151 of 766 Pages

9624

AB CR 79 - 2964 -

AB-CR-79-2964-3. Flight deck, frames 100 to 130, looking down and to port from point off starboard side. After expansion joint in deck appears just forward of elevator shaft.

SECRET

USS INDEPENDENCE (CVL22)
Page 152 of 766 Pages

9624



AB CR 79-2964 -

AB-CR-79-2964-4. Flight deck, frame 80 to 110, looking down and to port from point off starboard beam. Expansion joints in deck appears at right and left. The separation in the picture is a failure in the deck plating.

SECRET

USS INDEPENDENCE (CVL22)

Page 153 of 766 Pages

9624




AB CR - 2964 -

AB-CR-79-2964-5. Flight deck and after uptakes, frames 70 to 90, looking down and to port. Midship expansion joint occurs at frame 84 1/2. A separation in the flight deck appears at the extreme left. Note stacks carried away at flight deck level.

SECRET

USS INDEPENDENCE (CVL22)

Page 154 of 766 Pages




AB-CR-79-2964-6. After portion of island and flight deck in way of forward expansion joint, frames 50 to 70, looking down and to port from point off starboard beam. Note where stack has been carried away at flight deck level.

SECRET

USS INDEPENDENCE (CVL22)

Page 155 of 766 Pages



AB CR 79-2964-7

AB -CR-79-2964-7. Starboard face of island, frames 40 to 60, looking down and to port from point off starboard beam.

SECRET

USS INDEPENDENCE (CVL22)

Page 156 of 766 Pages

9624




AB-CR-79-2964-8. Flight deck and forward face of island, frames 40 to 50, looking down and to port.

SECRET

USS INDEPENDENCE (CVL22)

Page 157 of 766 Pages

9624



AB CR 79 - 2964 -

AB-CR-79-2964-9. Flight deck and forward portions of island, frames 30 to 60, looking down and to port from starboard.

SECRET

USS INDEPENDENCE (CVL22)
Page 158 of 766 Pages

9624



AB CR 79 - 2964 -

AB-CR-79-2964-11. Flight deck just forward of elevator shaft, frames 20 to 40, looking down and to port from starboard bow.

SECRET

USS INDEPENDENCE (CVL22)

Page 159 of 766 Pages

9324



AB CR 79 - 2964 - 10

AB-CR-79-2964-10. Flight deck just forward of elevator shaft, frames 10 to 40, looking down and to port from starboard.

SECRET

USS INDEPENDENCE (CVL22)

Page 160 of 766 Pages

9624




AB-CR-79-2964-12. Forward edge of flight deck and forecastle deck, looking down and to port from off starboard bow.

SECRET

USS INDEPENDENCE (CVL22)

Page 161 of 766 Pages

9624



AA-CR-65-1735-4

AA-CR-65-1735-4. Island structure and airplane crane before repairs,
taken from frame 40.

SECRET

USS INDEPENDENCE (CVL22)

Page 162 of 766 Pages

9624




AA-CR-175-2039-2. Flight deck from frame 37, looking aft.

SECRET

USS INDEPENDENCE (CVL22)
Page 163 of 766 Pages

9624




AA-CR-175-2040-6. Blast damage to crane and island structure, looking to starboard.

SECRET

USS INDEPENDENCE (CVL22)

Page 164 of 766 Pages

9624




AA-CR-175-2039-1. Island structure, looking forward and to starboard.
Note angle of crane and air defense level bulwark.

SECRET

USS INDEPENDENCE (CVL22)

Page 165 of 766 Pages

9624



1A CR234-1990-6

AA-CR-234-1990-6. Flight deck, looking to starboard from centerline at frame 57 note uptake and expansion joint.

SECRET

USS INDEPENDENCE (CVL22)

Page 166 of 766 Pages

9624




AA-CR-175-2040-7. Port air defense level, looking aft. Note raised out-board portion of deck and bulwark blown to starboard.

SECRET

USS INDEPENDENCE (CVL22)

Page 167 of 766 Pages

9624



AA-CR-175-2038-1. General view of flight deck looking forward from bridge. Canvas wind scoop, left center, covers bomb elevator trunk.

SECRET

USS INDEPENDENCE (CVL22)
Page 168 of 766 Pages

9624




AA-CR-175-2038-2. View of flight deck looking forward and to port from bridge level. Buckling of bulkhead 45 can be seen, lower left, below edge of elevator pit.

SECRET

USS INDEPENDENCE (CVL22)

Page 169 of 766 Pages

9624



AA-CR-175-2040-5. Blast damage to walkway and director sponson on port side between frames 17 and 30. Looking aft.

SECRET

USS INDEPENDENCE (CVL22)

Page 170 of 766 Pages

9624




AA-CR-65-1735-2. Blast damage to walkway and director sponson at frame 28, port side. Looking forward.

SECRET

USS INDEPENDENCE (CVL22)
Page 171 of 766 Pages

9624




AA-CR-65-1735-3. Flight deck, port side, looking aft. Showing blast damage to sponson at frame 40.

SECRET

USS INDEPENDENCE (CVL22)

Page 172 of 766 Pages

9624



AA-CR-59-2165-10. Damaged port gallery walkway and sponsons, frames 64 to 77.

SECRET

USS INDEPENDENCE (CVL22)
Page 173 of 766 Pages

9624




AA-CR-59-2165-11. Damaged gallery walkway and sponsons, port side, frames 68 to 88. Looking forward.

SECRET

USS INDEPENDENCE (CVL22)

Page 174 of 766 Pages

9624



CR234-1990-8


AA-CR-234-1990-8. Flight deck, port side, looking aft from about frame 45.

SECRET

USS INDEPENDENCE (CVL22)

Page 175 of 766 Pages

9624




AA-CR-234-1990-9. Flight deck, looking aft along centerline, and into hangar.

SECRET

Page 176 of 766 Pages

USS INDEPENDENCE (CVL22)

9624




AA-CR-65-1735-5. Flight deck, looking aft from frame 40.

SECRET

USS INDEPENDENCE (CVL22)

Page 177 of 766 Pages

9624



CR 175-2037 -

AA-CR-175-2037-12. Flight deck, looking aft along port side.

SECRET

USS INDEPENDENCE (CVL22)
Page 178 of 766 Pages

9624



AA CR 59-2167

AA-CR-59-2167-9. Forward elevator opening. Port side. Waterway distorted and broken over elevator guide rail.

SECRET

USS INDEPENDENCE (CVL22)

Page 179 of 766 Pages

9624




AA-CR-59-2165-1. Forward elevator. Forward, port, lock. Lock out 1", but not sheared; sheaves apparently undamaged. Safety latch bent outboard.

SECRET

USS INDEPENDENCE (CVL22)

Page 180 of 766 Pages

9624




AA-CR-59-2165-2. Forward elevator. After, port, lock out 1/4" but not sheared. Sheaves appear to be slightly warped. Safety latch broken and held by one bolt.

SECRET

USS INDEPENDENCE (CVL22)
Page 181 of 766 Pages

9624




AA-CR-59-2167-10. Forward elevator opening, starboard side, showing intact waterway over starboard elevator guide rail.

SECRET

USS INDEPENDENCE (CVL22)
Page 182 of 766 Pages

9624




AA-CR-59-2164-11. Forward elevator. Forward, starboard, lock. Lock flush and not sheared. Sheaves apparently undamaged. Safety latch extended sufficiently for plunger to clear hole.

SECRET

USS INDEPENDENCE (CVL22)
Page 183 of 766 Pages

9624



AA-CR-59-2164-12. Forward elevator, aft, starboard, lock. Lock flush and not sheared. Note bent waterway.

SECRET

USS INDEPENDENCE (CVL22)
Page 184 of 766 Pages

9624




AA CR 175-2038-5

AA-CR-175-2038-5. After edge of forward elevator opening from bridge level. Note remains of only plane left on this deck after blast.

SECRET

USS INDEPENDENCE (CVL22)
Page 185 of 766 Pages

9624



AA-CR-65-1736-1. Detail view of port side of flight deck at frame 61. Note burned over area of deck and radio mast. Burned area was under an airplane.

SECRET

USS INDEPENDENCE (CVL22)

Page 183 of 766 Pages

9624



AA-CR-175-2038-4. Flight deck, looking aft from bridge level.

SECRET

USS INDEPENDENCE (CVL22)
Page 187 of 766 Pages

9624



AB CR/00-2991 -

AA-CR-100-2991-3. After Baker. Flight deck. Looking aft and to port
at expansion joint at frame 63 1/2.

SECRET

USS INDEPENDENCE (CVL22)

Page 188 of 766 Pages

9624



AA-CR-175-2040-10. Flight deck expansion joint failure at centerline butt weld, frame 63 1/2. Looking aft.

SECRET

USS INDEPENDENCE (CVL22)

Page 189 of 766 Pages

9624



AA-CR-59-2164-7. Failure of centerline butt weld in flight deck expansion joint closing plate, frame 84 1/2. Looking aft.

SECRET

USS INDEPENDENCE (CVL22)

Page 190 of 766 Pages

9624



AA-CR-100-2991-5. After Baker. Flight deck. Looking forward along port side from frame 71.

SECRET

USS INDEPENDENCE (CVL22)

Page 191 of 766 Pages

9624



4A CR234-1990 - 5


AA-CR-234-1990-5. Flight deck, port side looking aft from frame 63 1/2.

SECRET

USS INDEPENDENCE (CVL22)

Page 192 of 766 Pages

9624




AA-CR-175-2040-9. Flight deck looking aft. Expansion joint faceplate, visible near instrument tower, is at frame No. 84 1/2.

SECRET

USS INDEPENDENCE (CVL22)

Page 193 of 766 Pages

9624



AB-CR-100-2991-4. After Baker. Flight deck. Looking aft along port side from frame 64.

SECRET

USS INDEPENDENCE (CVL22)
Page 194 of 766 Pages

9624




AA-CR-59-4148-6. Flight deck, port side, looking aft at frame 75. Note that there appear to be two longitudinal breaks in deck approximately parallel to deck edge.

SECRET

USS INDEPENDENCE (CVL22)

Page 195 of 766 Pages

9624




AA-CR-234-1990-7. Flight deck, looking at expansion joint frame 83 1/2 from frame 80.

SECRET

Page 196 of 766 Pages

USS INDEPENDENCE (CVL22)

9624



AA-CR175-2040-11. Flight deck expansion joint, failure at centerline butt weld, frame 84 1/2. Locking aft.

SECRET

USS INDEPENDENCE (CVL22)
Page 197 of 766 Pages

9624




AA-CR-59-2164-8. Failure of centerline butt weld in flight deck expansion joint closing plate, frame 84 1/2. Looking aft.

SECRET

USS INDEPENDENCE (CVL22)

Page 198 of 766 Pages

9624




AA-CR-59-2165-12. Flight deck. Looking aft along port side from about frame 88.

SECRET

USS INDEPENDENCE (CVL22)

Page 199 of 766 Pages

9624



AB CR/00-2991 -


AA-CR-100-2991-6. After Baker. Flight deck. Looking aft from about frame 88.

SECRET

USS INDEPENDENCE (CVL23)

Page 200 of 766 Pages

9624




AA-CR-175-2040-12. Flight deck, frame 95. Looking to starboard at 40 foot tear across center of deck.

SECRET

USS INDEPENDENCE (CVL22)

Page 201 of 766 Pages

9624



AA-CR-59-2165-7. Flight deck, frame 95. Slightly different angle than .
2040-12.

SECRET

USS INDEPENDENCE (CVL22)

Page 202 of 766 Pages

9624



AA-CR-175-2041-3. Flight deck looking forward along centerline between forward and after elevators, showing damage resulting from upward movement of flight deck.

SECRET

USS INDEPENDENCE (CVL22)

Page 203 of 766 Pages

9624




AA-CR-59-2165-8. Flight deck expansion joint frame 111 1/2. Looking to port. Joint open 5 1/2" starboard and 21" (far) port side.

SECRET

USS INDEPENDENCE (CVL22)

Page 204 of 766 Pages

9624




AA-CR-100-2991-7. After Baker. Flight deck. Looking to port along expansion joint at frame 111 1/2.

SECRET

USS INDEPENDENCE (CVL22)

Page 205 of 766 Pages

9624



AA-CR-175-2041-1. Flight deck expansion joint failure at centerline butt weld, frame 111 1/2. Looking aft. Note separation of joint.

SECRET

USS INDEPENDENCE (CVL22)

Page 206 of 766 Pages

9624



AA-CR-59-2165-9. Flight deck. Looking aft along port side from about frame 98. Note void in aft corner of flight deck.

SECRET

USS INDEPENDENCE (CVL22)
Page 207 of 766 Pages

9624



AA CR 59- 21

AA-CR-59-2167-12. After elevator opening, port side, showing intact waterway over port elevator guide rail. Rail bent.

SECRET

USS INDEPENDENCE (CVL22)

Page 208 of 766 Pages

9624




AA-CR-59-2165-4. After elevator. Forward, port, lock. Lock out 1" but not sheared.

SECRET

USS INDEPENDENCE (CVL22)

Page 209 of 766 Pages

9624



AA-CR-59-2165-3. After elevator. After, port, lock. Lock out 1" but not sheared. Auxiliary lock yolk bolt broken.

SECRET

USS INDEPENDENCE (CVL22)

Page 210 of 766 Pages

9624



AA-CR-59-2167-11. After elevator opening, starboard side, showing intact waterway over guide rail.

SECRET

USS INDEPENDENCE (CVL22)

Page 211 of 766 Pages

9624



AA-CR-65-2165-5. After elevator. Forward, starboard, lock. Lock flush and not sheared. Lock pedestal broken and offset about 2'.

SECRET

USS INDEPENDENCE (CVL22)

Page 212 of 766 Pages

9624



AA-CR-59-2165-6. After elevator. After, starboard, lock. Lock out 2" otherwise normal.

SECRET

USS INDEPENDENCE (CVL22)
Page 213 of 766 Pages

9624



AA-CR-175-2038-11. Flight deck. Looking forward along centerline.

SECRET

USS INDEPENDENCE (CVL22)

Page 214 of 766 Pages

9624



AA-CR-175-2038-6. After port corner of flight deck showing after edge bent up and deformation of beam at frame 138.

SECRET

USS INDEPENDENCE (CVL22)

Page 215 of 766 Pages

9624



AA-CR-175-2038-7. Flight deck looking to port Centered about frame 135. Note burned areas in wood decking.

SECRET

USS INDEPENDENCE (CVL22)
Page 216 of 766 Pages

9624




AA-CR-59-4148-3

AA-CR-59-4148-3. Flight deck. Void in way of missing aft port corner.

SECRET

USS INDEPENDENCE (CVL22)
Page 217 of 766 Pages

9624



AA-CR-59-2164-10. Failure of intermittent welds joining port side flight deck plating to longitudinal deck beams, frame 140 looking inboard and aft.

SECRET

USS INDEPENDENCE (CVL22)

Page 218 of 766 Pages

9624




AA-CR-59-2166-2. Gallery walkway, starboard side, looking forward from air defense level. Virtually no damage

SECRET

USS INDEPENDENCE (CVL22)

Page 219 of 766 Pages

9624




AA-CR-175-2040-4. Gallery walkway, starboard side, looking aft from surface lookout station. Note that airplane crane, frame 48, is virtually the first evidence of damage.

SECRET

USS INDEPENDENCE (CVL22)

Page 220 of 766 Pages

9624




CR 175 - 2039

AA-CR-175-2039-5. General view of flight deck looking aft from starboard forward corner.

SECRET

USS INDEPENDENCE (CVL22)
Page 221 of 766 Pages

9624



AA-CR-59-4148-8. Airplane crane after repairs. Starboard side, frame 48.

SECRET

USS INDEPENDENCE (CVL22)

Page 222 of 766 Pages

9624



AA-CR-65-1735-7

AA-CR-65-1735-7. Starboard side of flight deck. Looking forward from amidships.

SECRET

USS INDEPENDENCE (CVL22)

Page 223 of 766 Pages

9624



AA-CR-59-2166-1. Looking aft along starboard side of flight deck.
Taken from air defense level showing No. 3 and 4 smoke stacks.

SECRET

USS INDEPENDENCE (CVL22)

Page 224 of 766 Pages

9624




AA-CR-175-2040-8. General view looking aft on flight deck from frame 67. Open hatch, right center, is at frame 70.

SECRET

USS INDEPENDENCE (CVL22)

Page 225 of 766 Pages

9624




AA-CR-175-2038-12. Flight deck. Looking forward and to starboard, from about frame 98. Note remains of smokestacks.

SECRET

USS INDEPENDENCE (CVL22)

Page 226 of 766 Pages

9624




AA-CR-234-1990-10. Flight deck, looking aft to starboard at disorder.
Frame 80.

SECRET

USS INDEPENDENCE (CVL22)

Page 227 of 766 Pages

9624



AA-CR-59-4148 -

AA-CR-59-4148-7. Flight deck, starboard side, looking aft at frame 95.
Note that there appears to be but one longitudinal break in deck.

SECRET

USS INDEPENDENCE (CVL22)

Page 228 of 766 Pages

9624



AA-CR-65-1735-1

AA-CR-65-1735-6. Starboard side of flight deck. Looking aft from amidships.

SECRET

USS INDEPENDENCE (CVL22)

Page 229 of 766 Pages

9624



AA-CR-88-2100-7. Damaged port gallery walkway and sponsons, frame 39. Looking forward.

SECRET

USS INDEPENDENCE (CVL22)

Page 230 of 766 Pages

9624



AA-CR-175-2114-2. Damaged passageway door opening onto port gallery walkway, frame 127. Looking inboard.

SECRET

USS INDEPENDENCE (CVL22)

Page 231 of 766 Pages

9624



AA-CR-175-2114-3. Squadron gear locker door and port gallery walkway, frame 132. Looking inboard.

SECRET

USS INDEPENDENCE (CVL22)

Page 232 of 766 Pages

9624




AA-CR-175-2114-7. Galley deck, port side, showing torn shell plating and buckling of deck and transverse bulkhead at frame 134. Looking aft and to port. Note failure of bulkhead and shell connections to deck along welded joint.

SECRET

USS INDEPENDENCE (CVL22)

Page 233 of 766 Pages

9624



AA-CR-175-2114-5. Damage in crews shelter as seen from gallery door, port catwalk, frame 134.

SECRET

USS INDEPENDENCE (CVL22)

Page 234 of 766 Pages

9624



AA-CR-175-2114-4. Damage to gallery walkway and entrance to crew's shelter, frame 134, port side.

SECRET

USS INDEPENDENCE (CVL22)
Page 235 of 766 Pages

9624




AA-CR-175-2114-6. Looking aft at port side of bulkhead 138, gallery deck.

SECRET

USS INDEPENDENCE (CVL22)

Page 236 of 766 Pages

9624




AA-CR-175-2114-12. General view of damage to overhanging structure, port side, looking forward from flight deck, about frame 140.

SECRET

USS INDEPENDENCE (CVL22)

Page 237 of 766 Pages

9624



AA-CR-175-2039-11. Looking aft into stateroom 0301, starboard side, frame 37. Shock damage.

SECRET

USS INDEPENDENCE (CVL22)
Page 238 of 766 Pages




AA-CR-88-2100-8. Gallery level door in port shell from aviators ready room. Looking to port and forward at bulkhead 39.

SECRET

USS INDEPENDENCE (CVL22)

Page 239 of 766 Pages

9624



AA-CR-175-2036-12. Gallery deck, inboard joiner bulkhead, starboard side, frames 40 to 42. Looking forward and starboard.

SECRET

USS INDEPENDENCE (CVL22)
Page 240 of 766 Pages

9624




AA-CR-88-2100-6. Gallery deck, inboard joiner bulkhead, aviators ready room, frame 42. Looking forward. Bulkhead deflected towards blast.

SECRET

USS INDEPENDENCE (CVL22)

Page 241 of 766 Pages

9624




AA-CR-175-2039-10. Gallery deck, looking aft and inboard into state-room 0310, frame 37, port side, showing shock damage to joiner bulk-head, bunks and furniture.

SECRET

USS INDEPENDENCE (CVL22)

Page 242 of 766 Pages

9624




AA-CR-59-2227-12. Forward face of bulkhead 45. Looking to port and aft in C.I.C. room. Starboard side, gallery deck. Bulkhead bulged by blast in hangar space.

SECRET

USS INDEPENDENCE (CVL22)

Page 243 of 766 Pages

9624




AA-CR-59-2227-11. Forward face of bulkhead 45, looking aft and to starboard in Aviators ready room. Gallery deck level.

SECRET

USS INDEPENDENCE (CVL22)

Page 244 of 766 Pages

9624



AA-CR-59-2227-10. Looking to starboard just forward of bulkhead 45 on forecastle deck. Note bow in bulkhead stiffeners on right.

SECRET

USS INDEPENDENCE (CVL22)
Page 245 of 766 Pages

9624



AA-CR-175-2114-8. Poop deck, looking to starboard along after face of bulkhead 132 from opening in port shell. Debris in crew's berthing space.

SECRET

USS INDEPENDENCE (CVL22)

Page 246 of 766 Pages

9624



AA-CR-175-2114-1. Poop deck radio repair shop, C-0201-EL, frames 126 to 129, showing damage to port shell and failure of welded seam at deck. Looking outboard.

SECRET

USS INDEPENDENCE (CVL22)

Page 247 of 766 Pages

9624



AA-CR-175-2114-10. Poop deck. Damage in compartment adjacent to failures in port shell plating. Looking inboard and forward from frame 141.

SECRET

USS INDEPENDENCE (CVL22)

Page 248 of 766 Pages

9624



AA-CR-175-2114-9. Poop deck. Opening in port shell plating bulkheads 138 to 144.

SECRET

USS INDEPENDENCE (CVL22)

Page 249 of 766 Pages

9624



AA-CR-175-2114-11. Poop deck, frame 148, looking forward at bulkhead 138, port side. Showing damage to shell, bulkhead and poop deck plating.

SECRET

USS INDEPENDENCE (CVL22)
Page 250 of 766 Pages

9624

CONFIDENTIAL

Classification (~~Secret~~) (Changed to
Authority of Joint Chiefs of Staff (Action 15 Apr 49)
Date 21 April 1951
1st Lt. AFSWP

RESTRICTED
EXCLUDED FROM ACT 1948

CONFIDENTIAL



Defense Special Weapons Agency
6801 Telegraph Road
Alexandria, Virginia 22310-3398

TRC

9 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER
ATTENTION: OMI/Mr. William Bush

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency (formerly Defense Nuclear Agency) Security Office has reviewed and declassified the following reports:

+ ST-A

AD-366748 -	XRD-65
AD-366747 ~	XRD-64
AD-366746 ^	XRD-63
AD-376826 ~	XRD-60
AD-376824 ~	XRD-58
AD-376825 ~	XRD-59
AD-376823 ~	XRD-57
AD-376822 ~	XRD-56
AD-376821 ~	XRD-55
AD-366743 ~	XRD-54
AD-376820 ~	XRD-53
AD-366742 ~	XRD-52
AD-366741 ~	XRD-51
AD-366740 ~	XRD-50-Volume-2
AD-366739 -	XRD-49-Volume-1
AD-366738 -	XRD-48
AD-366737 ^	XRD-47

TRC

9 April 1997

SUBJECT: Declassification of Reports

AD-366736 -	XRD-46
AD-366735 -	XRD-45
AD-366723 -	XRD-37
AD-366721 -	XRD-35
AD-366717 -	XRD-31-Volume-2
AD-366716 -	XRD-30-Volume-1
AD-366751 -	XRD-68-Volume-2
AD-366750 -	XRD-67-Volume-1
AD-366752 -	XRD-69
AD-366744 -	XRD-61.

All of the cited reports are now **approved for public release**. **Distribution statement "A"** now applies.

Arndith Jarrett
ARDITH JARRETT
Chief, Technical Resource Center

Completed
1 mar 2000
B.W.